

Asbestos Policy

- 1. Asbestos is present on the Woodside Baptist Church site only on the roofs of the 'Fellowship Hall' and the 'Outreach Hall' where asbestos sheets were used.
- 2. The tiles are a concrete / Chrysotile (white) asbestos mix.
- 3. Any work requiring pressure on the roof will be done with appropriate boards to spread the load.
- 4. The tiles will be visually assessed every year for stability and to ensure that they are undisturbed.
- 5. The assessment will be carried out by church members with professional building or safety expertise
- 6. In the event of flaking or deterioration being observed, a professional assessment of the tile condition will be obtained.
- 7. If the condition of a roof is found to be unstable the entire roof will be removed and replaced with an approved material.

Policy adopted by CBM 24/09/07